



Copper Queen Branch/Freeport-McMoRan Corporation
36 West Highway 92
Bisbee, Arizona 85603

CERTIFIED MAIL 7008 1830 0001 1177 9032
RETURN RECEIPT REQUESTED

April 29, 2009

Ms. Cynthia S. Campbell
Manager Water Quality Compliance Section
Arizona Department of Environmental Quality
1110 West Washington Street
Phoenix, Arizona 85007

Re: Aquifer Characterization Report
Mitigation Order on Consent No. P-121-07

Dear Ms. Campbell:

Freeport-McMoRan Copper Queen Branch (CQB) herein submits three copies of the attached Aquifer Characterization Report. This Aquifer Characterization Report is a requirement of Section III.C of the Mitigation Order. The scope of the Aquifer Characterization Report covers the hydrologic investigations conducted from February 2008 through February 2009 in accordance with the Work Plan¹.

If you have any questions about this information please contact me at (520) 432-6206.

Sincerely,

A handwritten signature in black ink, appearing to read 'Rebecca A. Sawyer', written in a cursive style.

Rebecca A. Sawyer
Sr. Environmental Engineer
Freeport-McMoRan Copper Queen Branch

Attachments

cc: Sheila Deely (FCX)
Stuart Brown (Bridgewater Group)
James Norris (Hydro Geo Chem)

¹ Hydro Geo Chem, Inc. 2008. Revision 1 Work Plan to Characterize and Mitigate Sulfate with Respect to Drinking Water Supplies in the Vicinity of the Concentrator Tailing Storage Area, Cochise County, Arizona. July 3, 2008.